

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement: **20210819-S7171-40628001**
 Case Numbers: **21-005615**
 Date of Acc: **08/18/21**
 Time of Acc: **22:32** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY LEE REUVERS**
 Badge #: **71-4**
 Report Date: **08/19/2021**
 Officer Notified: **22:32** Hrs.
 Officer Arrived: **22:44** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00276508**
 Y-Coordinate: **04763654**
 Location Literal: **ORIOLE AVE**
 Description:

Unit 001

Driver Name - Last: VERDOORN	Bus Use:	Transported to:
First: LEVI		
Middle: JACOB	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: ARCHER		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51231		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 23	Undrriid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$15,000.00	
License State: IA	Ext of Damage: 4 - DISABLING DAMAGE	
License Class: A	First Event: 31 - ANIMAL	Carrier Name:
License Endorsmnt: N - TANK		Carrier Address:
License Restrictions: B	Second Event:	Carrier City:
Speed Limit: 55		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Fourth Event:	Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 1	Most Harmful Event: 31 - ANIMAL	HazMat Placard:
Vehicle Year: 2011	Abg Switch Stat:	Placard #:
Vehicle Make: FORD - FORD	Abg Deploy: 03 - NOT DEPLOYED	HazMat Released?:
Vehicle Model: F350 SUPER DUTY PICKUP	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Style: PICKUP	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Color: BROWN - BRO	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Vehicle Defect: 01 - NONE		Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 2:
Tow: 2 - DISABLED - PRIVATELY ARRANGED	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 3:
Tow #: 03 - SOUTH		Citation Charge 4:
Initial Trvl Dir: 03 - SOUTH		
Vision Obscured: 01 - NOT OBSCURED		

Property Damage 001

Object Damaged: COW CALF PAIR - LIVESTOCK	Company Owner Name:
Estimate of Damage: \$1,600.00	City: PAULLINA
Owner's Name - Last: WILSON	State: IA
First: DAN	Zip Code: 51046
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 06 - ANIMAL IN ROADWAY
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

Levi Verdoorn was driving his Ford F350 pickup south on Oriole Ave, when he struck an undetermined number of cattle standing on the traveled portion of the roadway. A cow and calf were killed in the accident. The cows and calves ran into the field and were identified as livestock belonging to Dan and Lorna Wilson, 4342 Pierce Ave. The livestock belonged at 5382 450th St location, but had gotten out and traveled approximately 3/4 of a mile where the accident occurred. Dan and Loran carry a farm policy through South O'Brien Insurance of Paullina, IA. Verdoorn privately arranged for his F350 to be towed by private vehicle.

Diagram

