

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Law Enforcement: **20211011-S7171-70742002**  
 Case Numbers: **21-007068**  
 Date of Acc: **10/11/21**  
 Time of Acc: **06:15** Hrs.  
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**  
 Officer: **DEPUTY LEE VELLEMA**  
 Badge #: **71-7**  
 Report Date: **10/11/2021**  
 Officer Notified: **06:15** Hrs.  
 Officer Arrived: **06:30** Hrs.

Scene Investigated: **YES**  
 Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **O'BRIEN - 71**  
 Acc Loc City:  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00271509**  
 Y-Coordinate: **04758690**  
 Location Literal: **IA 143 N**  
 Description:

**Unit 001**

Driver Name - Last: **KOEPP**  
 First: **JAMES**  
 Middle: **MARTIN**  
 City: **MARCUS**  
 State: **IA**  
 Zip: **51035**  
 Suffix:  
 Gender: **Male**  
 Age: **63**  
 CDL: **YES**  
 License State: **IA**  
 License Class: **B**  
 License Endorsmnt:  
 License Restrictions: **B**  
 Speed Limit:  
 Seating Position:  
 Driver Condition:  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **1**  
 Vehicle Year: **2012**  
 Vehicle Make: **CHEVROLET - CHEV**  
 Vehicle Model: **EQUINOX**  
 Vehicle Style: **UT**  
 Vehicle Color: **WHITE - WHI**  
 Vehicle Config: **03 - SPORT UTILITY VEHICLE**  
 Vehicle Defect:  
 Vehicle Action:  
 Tow: **3 - DISABLED - OFFICER ARRANGED**  
 Tow #: **HESSE**  
 Initial Trvl Dir:  
 Vision Obscured:

Bus Use:  
 Dvr Distractions: **02 - NOT DISTRACTED**  
 Traffic Controls:  
 Point of Init Impact:  
 Most Damaged Area:  
 Undrrid/Ovrid:  
 Rpr/Rplc Cost: **\$10,000.00**  
 Ext of Damage:  
 First Event:  
 Second Event:  
 Third Event:  
 Fourth Event:  
 Most Harmful Event:  
 Abg Switch Stat:  
 Abg Deploy:  
 Trapped:  
 Ejection:  
 Ejection Path:  
 Occpnt Protect:  
 Source of Trans: **01 - NOT TRANSPORTED**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func:  
 Emergency Status:  
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1:  
 Citation Charge 1:  
 Cit Chrg Code 2:  
 Citation Charge 2:  
 Citation Charge 3:  
 Citation Charge 4:

**Accident Environment**

First Harmful Event Loc:  
 Manner of Crash/Collision:  
 Light Conditions:  
 Weather Conditions:  
 Surface Conditions:  
 Workzone Related:  
 Activity:  
 Location:  
 Type:  
 Workers Present:

**Roadway Characteristics**

Environment:  
 Roadway:  
 Type of Road Junc/Feat:  
 FRA No.:  
 Horizontal Alignment:  
 Vertical Alignment:  
 First Harmful Evt of Crash: **31 - ANIMAL**

**Narrative**

Unit 1 was driving northbound on Highway 143 in the 4800 mile. As Unit 1 was northbound, a deer entered the roadway and Unit 1 struck the deer. Unit 1 sustained approximately \$10,000 worth of damage.

Diagram

