

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement: **20211020-S7171-70831001**
 Case Numbers: **21-007228**
 Date of Acc: **10/17/21**
 Time of Acc: **00:01** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY LEE VELLEMA**
 Badge #: **71-7**
 Report Date: **10/20/2021**
 Officer Notified: **12:06** Hrs.
 Officer Arrived: **12:19** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00294091**
 Y-Coordinate: **04761985**
 Location Literal: **460TH ST**
 Description:

Unit 001

Driver Name - Last: HANSEN	Bus Use:	Transported to:
First: SPENCER		
Middle: KEITH	Drvr Distractions: 99 - UNKNOWN	Transported by:
City: PAULLINA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51046		
Suffix:	Point of Init Impact: 14 - UNDERCARRIAGE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
Age: 27	Undrriid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$10,000.00	
License State: IA	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Class: C	First Event: 23 - VEHICLE WENT AIRBORNE	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:	Second Event: 03 - RAN OFF ROAD, LEFT	Carrier City:
Speed Limit: 50		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event: 20 - OVERTURN/ROLLOVER	Carrier Zip:
Driver Condition: 99 - UNKNOWN		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Fourth Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 1	Most Harmful Event: 20 - OVERTURN/ROLLOVER	HazMat Placard:
Vehicle Year: 2002	Abg Switch Stat:	Placard #:
Vehicle Make: DODGE - DODG	Abg Deploy: 04 - DEPLOYED FRONT OF PERSON	HazMat Released?:
Vehicle Model: DAKOTA	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Style: PK	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Color: RED - RED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1: 321.288(1)
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1: FAILURE TO MAINTAIN CONTROL
Vehicle Defect: 01 - NONE	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 2:
Tow: 2 - DISABLED - PRIVATELY ARRANGED		Citation Charge 3:
Tow #:		Citation Charge 4:
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 23 - VEHICLE WENT AIRBORNE
Type:	
Workers Present:	

Narrative

Unit 1 was traveling westbound on 460th St, which is a Level B roadway. Unit 1 crossed over Tyler Ave, which is a gravel road, and as Unit 1 crossed over Tyler Ave, the vehicle went airborne. The front end of Unit 1 gouged into the roadway of 460th St once it came back onto the roadway. Unit 1 then rolled over onto its top. Unit 1 went off of the roadway and entered a row of trees next to the roadway. The driver of Unit 1 sustained small scrapes to his left arm. Unit 1 sustained approximately \$10,000 worth of damage.

Diagram

