

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement Case Number: 22-001493	Scene Investigated: YES	At Intersection with:
Date of Acc: 03/05/22	Report to All Drivers:	Div HWay Trvl Dir:
Time of Acc: 20:15 Hrs.	Legal Intervention: NO	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	Private Property: NO	Direction 1:
Officer: DEPUTY JETT KORVER	County: O'BRIEN - 71	Distance 2:
Badge #: 71-8	Acc Loc City:	Direction 2:
Report Date: 03/05/2022	Acc Dir From City:	X-Coordinate: 00298233
Officer Notified: 20:16 Hrs.	Closest City:	Y-Coordinate: 04771416
Officer Arrived: 20:25 Hrs.	Miles From City:	Location Literal Description: 400TH ST MEASURING 2399 FEET EAST FROM VINE AVE
	Road, Street, HWay:	
	Definable Location:	
	Milepost Number:	

Unit 001

Driver Name - Last: KANAS FRANCIS	Bus Use:	Transported to: SPENCER HOSPITAL
Middle:	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: HARTLEY AMBULANCE
City: SALEM	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: OR	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Zip: 97301	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
Suffix:	Undrrid/Ovrid: 9 - UNKNOWN	
Gender: Male	Rpr/Rplc Cost: \$5,000.00	Carrier Name:
Age: 38	Ext of Damage: 4 - DISABLING DAMAGE	Carrier Address:
CDL: NO	First Event: 04 - CROSSED CENTERLINE (UNDIVIDED)	Carrier City:
License State: OR	Second Event: 03 - RAN OFF ROAD, LEFT	Carrier State:
License Class: C	Third Event: 44 - DITCH	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event: 44 - DITCH	Number of Axles:
Speed Limit: 55	Abg Switch Stat:	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 03 - NOT DEPLOYED	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Total Occupants: 4	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Year: 2019	Source of Trans: 03 - EMS GROUND	Cit Chrg Code 1:
Vehicle Make: DODGE - DODG	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: GRAND CARAVAN S		Cit Chrg Code 2:
Vehicle Style:		Citation Charge 2:
Vehicle Color: GRAY - GRY		Citation Charge 3:
Vehicle Config: 01 - PASSENGER CAR		Citation Charge 4:
Vehicle Defect: 01 - NONE		
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #: 22000025		
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 02 - SHOULDER	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 02 - WEATHER CONDITION
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 04 - FREEZING RAIN/DRIZZLE	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 03 - ICE/FROST	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 44 - DITCH
Type:	
Workers Present:	

Injured Person 001

Name - Last:	RUES	Airbag Deployment:	03 - NOT DEPLOYED
First:	RICHE	Airbag Switch Status:	
Middle:		Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	3 - SUSPECTED MINOR/NON-INCAPACITATING
City:	MARATON	Ejection:	2 - NOT EJECTED
State:	IA	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
Zip Code:	50565	Alcohol Test Given:	
Age:	42	Drug Test Given:	
Sex:	FEMALE	Source of Transport:	03 - EMS GROUND
Unit No.:	1	Died at Scene/Enroute:	01 - NOT APPLICABLE
Seating Position:	03 - 1ST ROW: RIGHT SIDE	Transported to:	PRIMGAR HOSPITAL
Occupant Protection:	03 - SHOULDER AND LAP BELT USED	Transported by:	SUTHERLAND AMBULANCE

Injured Person 002

Name - Last:	SALIK	Airbag Deployment:	03 - NOT DEPLOYED
First:	ELENY	Airbag Switch Status:	
Middle:		Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	3 - SUSPECTED MINOR/NON-INCAPACITATING
City:		Ejection:	2 - NOT EJECTED
State:		Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
Zip Code:		Alcohol Test Given:	
Age:	31	Drug Test Given:	
Sex:	FEMALE	Source of Transport:	03 - EMS GROUND
Unit No.:	1	Died at Scene/Enroute:	01 - NOT APPLICABLE
Seating Position:	04 - 2ND ROW: LEFT SIDE	Transported to:	SPENCER HOSPITAL
Occupant Protection:	03 - SHOULDER AND LAP BELT USED	Transported by:	HARTLEY AMBULANCE

Injured Person 003

Name - Last:	BEURET	Airbag Deployment:	03 - NOT DEPLOYED
First:	RINTIA	Airbag Switch Status:	
Middle:		Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	3 - SUSPECTED MINOR/NON-INCAPACITATING
City:		Ejection:	1 - NOT APPLICABLE
State:		Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
Zip Code:		Alcohol Test Given:	
Age:	21	Drug Test Given:	
Sex:	FEMALE	Source of Transport:	03 - EMS GROUND
Unit No.:	1	Died at Scene/Enroute:	01 - NOT APPLICABLE
Seating Position:	06 - 2ND ROW: RIGHT SIDE	Transported to:	PRIMGAR HOSPITAL
Occupant Protection:	02 - NONE USED	Transported by:	SUTHERLAND AMBULANCE

Narrative

Unit one was traveling west on B40 when the driver hit the brake to slow down for the icy roads. When the driver hit the brake the van began to slide. The van crossed the center line and entered the south ditch and came to rest in the corn field south of the roadway. All four people in the vehicle complained of pain and were transported by EMS ground.

Diagram

