

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22-001605**
 Date of Acc: **03/10/22**
 Time of Acc: **16:30** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY TIMOTHY ROHRBAUGH**
 Badge #: **71-5**
 Report Date: **03/10/2022**
 Officer Notified: **16:51** Hrs.
 Officer Arrived: **17:20** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00273285**
 Y-Coordinate: **04763927**
 Location Literal: **OAK HILL AVE**
 Description:

Unit 001

Driver Name - Last: **RICHTER**
 First: **AUSTIN**
 Middle: **JAMES**
 City: **PAULLINA**
 State: **IA**
 Zip: **51046-0000**
 Suffix:
 Gender: **Male**
 Age: **29**
 CDL: **YES**
 License State: **IA**
 License Class: **A**
 License Endorsmnt: **N - TANK**
 License Restrictions:
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2009**
 Vehicle Make: **PETERBILT - PTRB**
 Vehicle Model: **386**
 Vehicle Style: **CON**
 Vehicle Color: **SILVER - SIL**
 Vehicle Config: **13 - TRACTOR/SEMI-TRAILER**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **2 - DISABLED - PRIVATELY ARRANGED**
 Tow #:
 Initial Trvl Dir: **01 - NORTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **14 - REACHING FOR OBJECT(S) /FALLEN OBJECT(S)**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **01 - FRONT PASSENGER SIDE CORNER**
 Most Damaged Area: **16 - CARGO LOSS**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$50,000.00**
 Ext of Damage: **5 - SEVERE, VEHICLE TOTALED**
 First Event: **01 - RAN OFF ROAD, RIGHT**
 Second Event: **20 - OVERTURN/ROLLOVER**
 Third Event: **08 - CARGO/EQUIPMENT LOSS OR SHIFT**
 Fourth Event:
 Most Harmful Event: **01 - RAN OFF ROAD, RIGHT**
 Abg Switch Stat:
 Abg Deploy: **01 - NOT APPLICABLE**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **1 - NOT APPLICABLE**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**
5 - UNINJURED

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **03 - DUMP (GRAIN/GRAVEL)**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Accident Environment

First Harmful Event Loc: **01 - ON ROADWAY**
 Manner of Crash/Collision: **01 - NON-COLLISION (SINGLE VEHICLE)**
 Light Conditions: **1 - DAYLIGHT**
 Weather Conditions: **01 - CLEAR**
 Surface Conditions: **01 - DRY**
 Workzone Related: **NO**
 Activity:
 Location:
 Type:
 Workers Present:

Roadway Characteristics
 Environment: **01 - NONE APPARENT**
 Roadway: **01 - NONE APPARENT**
 Type of Road Junc/Feat: **01 - NON-JUNCTION/NO SPECIAL FEATURE**
 FRA No.:
 Horizontal Alignment:
 Vertical Alignment:
 First Harmful Evt of Crash: **20 - OVERTURN/ROLLOVER**

Narrative

Unit 1 was traveling north on Oak Hill Ave. in the 4500 mile. The driver reach for a water bottle and ran off the road to the right. The vehicle entered the ditch and overturned on a field driveway spilling the load of corn into the field and the ditch.

Diagram

