

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22-2492**
 Date of Acc: **04/18/22**
 Time of Acc: **19:30** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY LEE REUVERS**
 Badge #: **71-4**
 Report Date: **04/18/2022**
 Officer Notified: **19:37** Hrs.
 Officer Arrived: **19:46** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00281933**
 Y-Coordinate: **04784965**
 Location Literal: **REDWING AVE**
 Description:

Unit 001

Driver Name - Last: **SYBESMA**
 First: **MYA**
 Middle: **JILL**
 City: **SANBORN**
 State: **IA**
 Zip: **51248**
 Suffix:
 Gender: **Female**
 Age: **15**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions: **7**
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2010**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **TRAVERSE LTZ**
 Vehicle Style: **SUV**
 Vehicle Color: **GRAY - GRY**
 Vehicle Config: **03 - SPORT UTILITY VEHICLE**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **02 - EAST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **04 - STOP SIGNS**
 Point of Init Impact: **08 - REAR DRIVER SIDE**
 Most Damaged Area: **08 - REAR DRIVER SIDE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$5,000.00**
 Ext of Damage: **3 - FUNCTIONAL DAMAGE**
 First Event: **72 - HIT AND RUN**
 Second Event: **03 - RAN OFF ROAD, LEFT**
 Third Event:
 Fourth Event:
 Most Harmful Event: **72 - HIT AND RUN**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION, 98 - OTHER (EXPLAIN IN NARRATIVE)**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: CRUZ RAMIREZ	Bus Use:	Transported to:
First: SANTOS		
Middle: GUILLERMO	Drvr Distractions: 99 - UNKNOWN	Transported by:
City: SHELDON		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51201-1270		
Suffix:	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 02 - RAN STOP SIGN
Age: 34	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$3,000.00	
License State: IA	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: 0	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt:		Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit: 55	Second Event: 72 - HIT AND RUN	Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier State:
Driver Condition: 99 - UNKNOWN	Fourth Event:	Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE		
Total Occupants: 1		Number of Axles:
Vehicle Year: 2009		HazMat Involvement:
Vehicle Make: MERCURY - MERC		HazMat Placard:
Vehicle Model: SABLE	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Style: SEDAN	Abg Switch Stat:	HazMat Released?:
Vehicle Color: MULTICOLORED - MUL/COL	Abg Deploy: 03 - NOT DEPLOYED	Converter Dolly:
Vehicle Config: 01 - PASSENGER CAR	Trapped: 1 - NOT TRAPPED/APPLICABLE	GVWR:
Vehicle Defect: 99 - UNKNOWN	Ejection: 2 - NOT EJECTED	Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Citation Charge 1:
Tow: 1 - DRIVEN AWAY	Occpnt Protect: 99 - UNKNOWN	Cit Chrg Code 2:
Tow #:		Citation Charge 2:
Initial Trvl Dir: 03 - SOUTH		
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 3:
	Died at Scene: 01 - NOT APPLICABLE	
		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 05 - BROADSIDE (FRONT TO SIDE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 72 - HIT AND RUN
Workers Present:	

Narrative

Unit 1 was traveling eastbound on Highway 18 (320th St) when a maroon Ford car was traveling southbound on Redwing Ave. The Ford car fail to obey the stop sign and collided with Unit 1 near the rear drivers wheel. The collision forced Unit 1 into the north ditch of 320th St. Unit 2 fled the scene without stopping and continued south on Redwing Ave. The maroon Ford car sustained considerable front driver side damage. A headlight and accessory lights were identified to be Ford by a logo. Driver of Unit 1, Mya, operated the motor vehicle in a proper manner and was the victim of a hit and run. Three arrest warrants were filed for Driver of Unit 2, Fail to Obey Stop Sign, No Valid Driver's License, and Leaving the Scene of a Property Damage Accident. Santos Guillermo Cruz Ramirez has allegedly fled the area.

Diagram

