

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22-006717**
 Date of Acc: **09/16/22**
 Time of Acc: **16:20** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY TIMOTHY ROHRBAUGH**
 Badge #: **71-5**
 Report Date: **09/16/2022**
 Officer Notified: **16:25** Hrs.
 Officer Arrived: **16:25** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00271611**
 Y-Coordinate: **04762584**
 Location Literal: **IA 143 N**
 Description:

Unit 001

Driver Name - Last: **MILLER**
 First: **BYRON**
 Middle: **DANIEL**
 City: **MARCUS**
 State: **IA**
 Zip: **51035-0000**
 Suffix:
 Gender: **Male**
 Age: **60**
 CDL: **YES**
 License State: **IA**
 License Class: **A**
 License Endorsmnt:
 License Restrictions:
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2007**
 Vehicle Make: **MACK - MACK**
 Vehicle Model:
 Vehicle Style: **DUMP**
 Vehicle Color: **WHITE - WHI**
 Vehicle Config: **11 - TRUCK/TRAILER**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **09 - BACKING**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **03 - SOUTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **04 - STOP SIGNS**
 Point of Init Impact: **06 - REAR MIDDLE**
 Most Damaged Area: **06 - REAR MIDDLE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$500.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Third Event:
 Fourth Event:
 Most Harmful Event: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Abg Switch Stat:
 Abg Deploy: **01 - NOT APPLICABLE**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **1 - NOT APPLICABLE**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **19 - STARTING OR BACKING IMPROPERLY**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **03 - DUMP (GRAIN/GRAVEL)**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: JOHNSON	Bus Use:	Transported to:
First: NEIL		
Middle: MARVIN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: PAULLINA		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51046-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 74	Undrriid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$6,000.00	
License State: IA	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: B	Second Event:	Carrier City:
Speed Limit: 55	Third Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 2		HazMat Placard:
Vehicle Year: 2020	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: HONDA - HOND	Abg Switch Stat:	HazMat Released?:
Vehicle Model: PLT	Abg Deploy: 03 - NOT DEPLOYED	Converter Dolly:
Vehicle Style: UT		GVWR:
Vehicle Color: SILVER - SIL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Ejection: 2 - NOT EJECTED	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 11 - STOPPED IN TRAFFIC	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #:	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
Initial Trvl Dir: 03 - SOUTH	Died at Scene: 01 - NOT APPLICABLE	
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

VEHICLE # 1 IS A SEMI DUMP TRUCK PULLING A PUP DUMP TRAILER. VEHICLE #1 WAS SITTING AT THE STOP SIGN ON NETTLE AVE HEADING SOUTH. THERE WAS CONSTRUCTION IN HIS LANE ACROSS HIGHWAY 10 AND IN THE EAST BOUND HIGHWAY 10 LANE WEST OF THE INTERSECTION. THERE WAS A WEST BOUND HIGHWAY 10 SEMI AND TRAILER TURNING RIGHT TO GO NORTH ON NETTLE AVE. VEHICLE # 1 CHECKED HIS MIRROR AND PROCEEDED TO BACK UP TO GIVE THE TURNING SEMI ROOM TO MAKE THE TURN. VEHICLE #1 DID NOT SEE THAT VEHICLE #2 WAS SITTING STOPPED BEHIND HIM. VEHICLE # 1 BACKED INTO VEHICLE #2.

Diagram

