

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22-007544**
 Date of Acc: **10/15/22**
 Time of Acc: **09:52** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY JETT KORVER**
 Badge #: **71-8**
 Report Date: **10/15/2022**
 Officer Notified: **09:53** Hrs.
 Officer Arrived: **10:02** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00269030**
 Y-Coordinate: **04772426**
 Location Literal: **400TH ST**
 Description:

Unit 001

Driver Name - Last: **FLORES**
 First: **JEWELL**
 Middle: **LARA**
 City: **HULL**
 State: **IA**
 Zip: **51239**
 Suffix:
 Gender: **Female**
 Age: **21**
 CDL: **NO**
 License State: **IA**
 License Class: **0**
 License Endorsmnt:
 License Restrictions:
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **06 - UNDER THE INFLUENCE O**
 Alcohol Test Given: **YES**
 Drug Test Given: **2 - BLOOD**
 Total Occupants: **1**
 Vehicle Year: **2004**
 Vehicle Make: **HONDA - HOND**
 Vehicle Model: **CIVIC EX**
 Vehicle Style: **4D**
 Vehicle Color: **GOLD - GLD**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **3 - DISABLED - OFFICER ARRANGED**
 Tow #: **22-00103**
 Initial Trvl Dir: **04 - WEST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Most Damaged Area: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Undrrid/Ovrid: **9 - UNKNOWN**
 Rpr/Rplc Cost: **\$3,500.00**
 Ext of Damage: **5 - SEVERE, VEHICLE TOTALED**
 First Event: **03 - RAN OFF ROAD, LEFT**
 Second Event: **44 - DITCH**
 Third Event:
 Fourth Event:
 Most Harmful Event: **44 - DITCH**
 Abg Switch Stat:
 Abg Deploy: **04 - DEPLOYED FRONT OF PERSON**
 Trapped: **2 - EXTRICATED BY NON-MECHAN**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **03 - EMS GROUND**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to: **SANFORD SHELDON**
 Transported by: **HOSPERS AMBULANCE**
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **03 - EXCEEDED AUTHORIZED SPEED, 08 - OPERATING VEHICLE IN A RECKLESS, ERRATIC, CARELESS, NEGLIGENT MANNER**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Accident Environment

First Harmful Event Loc: **01 - ON ROADWAY**
 Manner of Crash/Collision: **01 - NON-COLLISION (SINGLE VEHICLE)**
 Light Conditions: **1 - DAYLIGHT**
 Weather Conditions: **01 - CLEAR**
 Surface Conditions: **01 - DRY**
 Workzone Related: **NO**
 Activity:
 Location:
 Type:
 Workers Present:

Roadway Characteristics
 Environment: **01 - NONE APPARENT**
 Roadway: **01 - NONE APPARENT**
 Type of Road Junc/Feat: **01 - NON-JUNCTION/NO SPECIAL FEATURE**
 FRA No.:
 Horizontal Alignment:
 Vertical Alignment:
 First Harmful Evt of Crash: **44 - DITCH**

Narrative

Unit one was west bound in the 4800-MI of 400th Street following her ex-boyfriend. According to witnesses, and confirmed by a cell phone video taken by one of the witnesses, the driver of unit one was driving at high rates of speed and upon getting close behind her ex-boyfriend, suddenly, and with no obvious reason, the driver of unit one veered hard to the left (south) and entered the south ditch where unit one rolled over 4 times according to witnesses. The driver of unit one suffered severe injuries and was transported to the Sheldon Hospital where she was later taken by helicopter to Sanford Sioux Falls. Drugs and alcohol are suspected to be factors in this crash. The investigation is ongoing.



VEHICLE UNIT 1 WAS
FOLLOWING-NO VEH
CONTACT

