

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22007326**
 Date of Acc: **10/07/22**
 Time of Acc: **15:30** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY BRAD STEVENS**
 Badge #: **71-10**
 Report Date: **10/08/2022**
 Officer Notified: **15:31** Hrs.
 Officer Arrived: **15:41** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00303163**
 Y-Coordinate: **04771886**
 Location Literal: **YELLOW AVE**
 Description:

Unit 001

Driver Name - Last: CAVEN	Bus Use:	Transported to:	N/A
First: JOSEPH		Transported by:	N/A
Middle: MICHAEL	Drvr Distractions: 98 - DISTRACTION OUTSIDE VEHICLE (EXPLAIN IN NARRATIVE)	Special Veh Func:	01 - NO SPECIAL FUNCTION
City: SPENCER	Traffic Controls: 01 - NO CONTROLS PRESENT	Emergency Status:	01 - NOT APPLICABLE
State: IA	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	50 - VISION OBSTRUCTED
Zip: 51301	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Carrier Name:	MGP FARMS LLC
Suffix:	Undrrid/Ovrid: 1 - NONE	Carrier Address:	3580 270TH AVE
Gender: Male	Rpr/Rplc Cost: \$8,700.00	Carrier City:	SPENCER
Age: 64	Ext of Damage: 4 - DISABLING DAMAGE	Carrier State:	IA
CDL: YES	First Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier Zip:	51301-7592
License State: IA	Second Event: 33 - VEHICLE IN TRAFFIC	Cargo Body Type:	99 - UNKNOWN
License Class: A	Third Event: 01 - RAN OFF ROAD, RIGHT	Number of Axles:	3
License Endorsmnt:	Fourth Event:	HazMat Involvement:	02 - NO
License Restrictions: B	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	HazMat Placard:	
Speed Limit: 55	Abg Switch Stat:	Placard #:	
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 01 - NOT APPLICABLE	HazMat Released?:	
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:	2
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	GVWR:	3 - 26,001 LBS OR MORE
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:	
Total Occupants: 1	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:	
Vehicle Year: 2006	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 2:	
Vehicle Make: INTERNATIONAL - INTL	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Model: 9400I SBA		Citation Charge 3:	
Vehicle Style: DS		Citation Charge 4:	
Vehicle Color: WHITE - WHI			
Vehicle Config: 13 - TRACTOR/SEMI-TRAILER			
Vehicle Defect: 01 - NONE			
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT			
Tow: 2 - DISABLED - PRIVATELY ARRANGED			
Tow #:			
Initial Trvl Dir: 03 - SOUTH			
Vision Obscured: 15 - FOG/SMOKE/DUST			

Unit 002

Driver Name - Last: KRUSE	Bus Use:	Transported to: N/A
First: KEITH		
Middle: ROGER	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: N/A
City: EVERLY		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51338		
Suffix:	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Drvr: 50 - VISION OBSTRUCTED
Age: 66	Undrrid/Ovrid: 1 - NONE	
CDL: YES	Rpr/Rplc Cost: \$5,200.00	
License State: IA	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: A	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name: KRUSE FARMS
License Endorsmnt:		Carrier Address: 1235 360TH ST
License Restrictions:		Carrier City: EVERLY
Speed Limit: 55	Second Event:	Carrier State: IA
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier Zip: 51338-7545
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Cargo Body Type: 03 - DUMP (GRAIN/GRAVEL)
Alcohol Test Given: NO		Number of Axles: 3
Drug Test Given: 1 - NONE		HazMat Involvement: 02 - NO
Total Occupants: 1		HazMat Placard:
Vehicle Year: 1991	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: INTERNATIONAL - INTL	Abg Switch Stat:	HazMat Released?:
Vehicle Model: 9000	Abg Deploy: 01 - NOT APPLICABLE	Converter Dolly: 2
Vehicle Style: TL		GVWR: 3 - 26,001 LBS OR MORE
Vehicle Color: WHITE - WHI	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 08 - SINGLE-UNIT TRUCK (>=3 AXLES)	Ejection: 2 - NOT EJECTED	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Vehicle Action: 03 - TURNING RIGHT		Citation Charge 3:
Tow: 1 - DRIVEN AWAY	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	
Tow #:		
Initial Trvl Dir: 03 - SOUTH		
Vision Obscured: 15 - FOG/SMOKE/DUST		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 03 - VISUAL OBSTRUCTION
Light Conditions: 1 - DAYLIGHT	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 01 - CLEAR, 10 - BLOWING SAND, SOIL, DIRT	Type of Road Junc/Feat: 04 - DRIVEWAY ACCESS (WITHIN)
Surface Conditions: 01 - DRY	FRA No.:
	Horizontal Alignment:
Workzone Related: NO	Vertical Alignment:
Activity:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Location:	
Type:	
Workers Present:	

Narrative

UNIT 1 WAS SOUTHBOUND IN THE 3900 MILE OF YELLOW AVE. UNIT 2 WAS SOUTHBOUND IN FRONT OF UNIT 1 ATTEMPTING TO TURN RIGHT INTO A FIELD DRIVE. DUE TO SIGNIFICANT DUST FROM THE GRAVEL ROAD, NEITHER UNIT WAS ABLE TO SEE ONE ANOTHER, AND COLLIDED AS UNIT 2 WAS ATTEMPTING TO MAKE THE TURN INTO A FIELD DRIVE.

