

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **22-008227**
 Date of Acc: **11/09/22**
 Time of Acc: **16:00** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY BRAD STEVENS**
 Badge #: **71-10**
 Report Date: **11/10/2022**
 Officer Notified: **16:19** Hrs.
 Officer Arrived: **16:28** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00279836**
 Y-Coordinate: **04769983**
 Location Literal: **POLK AVE**
 Description:

Unit 001

Driver Name - Last: COULDREN	Bus Use:	Transported to:
First: MICHELLE		
Middle: LYNN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: PAULLINA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51046		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female		
Age: 63	Most Damaged Area: 14 - UNDERCARRIAGE	Cont. Circum., Drvr: 06 - LOST CONTROL, 18 - SWERVED TO AVOID: VEHICLE, OBJECT, NON-MOTORIST, OR ANIMAL IN ROADWAY
CDL: NO	Undrriid/Ovrid: 1 - NONE	
License State: IA	Rpr/Rplc Cost: \$1,600.00	
License Class: C	Ext of Damage: 2 - MINOR DAMAGE	
License Endorsmnt:	First Event: 13 - ANIMAL (AVOIDED HITTING)	
License Restrictions: B		Carrier Name:
Speed Limit: 55		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier City:
Driver Condition: 99 - UNKNOWN		Carrier State:
Alcohol Test Given: NO	Third Event: 03 - RAN OFF ROAD, LEFT	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1	Fourth Event: 95 - OTHER NON-COLLISION (EXPLAIN IN NARRATIVE)	Number of Axles:
Vehicle Year: 2006		HazMat Involvement:
Vehicle Make: FORD - FORD	Most Harmful Event: 95 - OTHER NON-COLLISION (EXPLAIN IN NARRATIVE)	HazMat Placard:
Vehicle Model: EXPEDITION		Placard #:
Vehicle Style: LL	Abg Switch Stat:	HazMat Released?:
Vehicle Color: BLACK - BLK	Abg Deploy: 03 - NOT DEPLOYED	Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE		GVWR:
Vehicle Defect: 01 - NONE	Trapped: 2 - EXTRICATED BY NON-MECHAN	Cit Chrg Code 1:
	Ejection: 2 - NOT EJECTED	Citation Charge 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Tow: 4 - NOT DISABLED - PRIVATELY ARRANGED	Occpnt Protect: 99 - UNKNOWN	Citation Charge 2:
Tow #:		
Initial Trvl Dir: 03 - SOUTH		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 06 - ANIMAL IN ROADWAY
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 06 - MUD, DIRT	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 31 - ANIMAL
Workers Present:	

Narrative

Unit 1 was southbound in the 4100 mile of Polk Ave. Driver of Unit 1 stated a deer ran into the roadway and she swerved to miss it, causing Unit 1 to go off of the roadway and down into a creek. The front of Unit 1 was submerged in the creek. **** ReExam Reason: MULTIPLE INCIDENTS WHERE SHE HAS FALLEN ASLEEP BEHIND THE WHEEL. FAMILY BELIEVES SHE IS OFF OF HER MEDS AND ISNT SAFE TO DRIVE

Diagram

