

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement Case Number: 22-009054	Scene Investigated: NO	At Intersection with:
Date of Acc: 12/14/22	Report to All Drivers:	Div HWay Trvl Dir:
Time of Acc: 21:05 Hrs.	Legal Intervention: NO	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	Private Property: NO	Direction 1:
Officer: DEPUTY JETT KORVER	County: O'BRIEN - 71	Distance 2:
Badge #: 71-8	Acc Loc City:	Direction 2:
Report Date: 12/14/2022	Acc Dir From City:	X-Coordinate: 00297597
Officer Notified: 21:06 Hrs.	Closest City:	Y-Coordinate: 04774184
Officer Arrived: 21:11 Hrs.	Miles From City:	Location Literal Description: VINE AVE MEASURING 2065 FEET SOUTH FROM 380TH ST
	Road, Street, HWay:	
	Definable Location:	
	Milepost Number:	

Unit 001

Driver Name - Last: WILBORN	Bus Use:	Transported to:
First: TIMOTHY		
Middle: JOSE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: DES MOINES	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Zip: 50314	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender: Male	Rpr/Rplc Cost: \$10,000.00	
Age: 43	Ext of Damage: 4 - DISABLING DAMAGE	
CDL: NO	First Event: 01 - RAN OFF ROAD, RIGHT	Carrier Name:
License State: IA		Carrier Address:
License Class: D	Second Event: 44 - DITCH	Carrier City:
License Endorsmnt: 3 - PASS VEH LESS THAN 16 P	Third Event:	Carrier State:
License Restrictions: B	Fourth Event:	Carrier Zip:
Speed Limit: 55	Most Harmful Event: 44 - DITCH	Cargo Body Type: 01 - NOT APPLICABLE
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Switch Stat:	Number of Axles:
Driver Condition: 01 - APPARENTLY NORMAL	Abg Deploy: 03 - NOT DEPLOYED	HazMat Involvement:
Alcohol Test Given: NO	Trapped: 2 - EXTRICATED BY NON-MECHAN	HazMat Placard:
Drug Test Given: 1 - NONE	Ejection: 2 - NOT EJECTED	Placard #:
Total Occupants: 1	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	HazMat Released?:
Vehicle Year: 2004	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Converter Dolly:
Vehicle Make: CHEVROLET - CHEV	Source of Trans: 01 - NOT TRANSPORTED	GVWR:
Vehicle Model: AVALANCHE K1500	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Style: PK		Citation Charge 1:
Vehicle Color: WHITE - WHI		Cit Chrg Code 2:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Citation Charge 2:
Vehicle Defect: 01 - NONE		Citation Charge 3:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 4:
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #: 22-00138		
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 03 - ICE/FROST	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 44 - DITCH
Type:	
Workers Present:	

Narrative

Unit one was north bound in 3800-mile of Vine Ave. Vine Ave was completely ice covered at the time of the accident. The driver of unit one stated he was driving below the speed limit but lost control of the vehicle and it entered the east ditch coming to rest on the driver's side. The driver was not injured.

