

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Law Enforcement	Scene Investigated: <b>YES</b>	At Intersection with:
Case Number: <b>23-001442</b>	Report to All Drivers:	Div HWay Trvl Dir:
Date of Acc: <b>03/05/23</b>	Legal Intervention: <b>NO</b>	Distance 1:
Time of Acc: <b>18:32</b> Hrs.	Private Property: <b>NO</b>	Direction 1:
Name of Agency: <b>O'BRIEN COUNTY SHERIFF'S OFF</b>	County: <b>O'BRIEN - 71</b>	Distance 2:
Officer:	Acc Loc City:	Direction 2:
<b>DEPUTY JETT KORVER</b>	Acc Dir From City:	X-Coordinate: <b>00300927</b>
Badge #: <b>71-8</b>	Closest City:	Y-Coordinate: <b>04756360</b>
Report Date: <b>03/05/2023</b>	Miles From City:	Location Literal: <b>WILSON AVE MEASURING 138</b>
Officer Notified: <b>18:32</b> Hrs.	Road, Street, HWay:	Description: <b>FEET SOUTH FROM IA 10 E</b>
Officer Arrived: <b>18:49</b> Hrs.	Definable Location:	
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>MAGEE</b>	Bus Use:	Transported to:
First: <b>BENJAMIN</b>		
Middle: <b>REED</b>	Drvtr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>SUTHERLAND</b>	Traffic Controls:	Special Veh Func:
State: <b>IA</b>	Point of Init Impact:	Emergency Status:
Zip: <b>51058-0000</b>	Most Damaged Area:	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Suffix:	Undrrid/Ovrid:	
Gender: <b>Male</b>	Rpr/Rplc Cost: <b>\$10,000.00</b>	Carrier Name:
Age: <b>34</b>	Ext of Damage:	Carrier Address:
CDL: <b>NO</b>	First Event:	Carrier City:
License State: <b>IA</b>	Second Event:	Carrier State:
License Class: <b>C</b>	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
License Restrictions:	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: <b>NO</b>	Ejection:	HazMat Released?:
Drug Test Given: <b>1 - NONE</b>	Ejection Path:	Converter Dolly:
Total Occupants: <b>1</b>	Occpnt Protect:	GVWR:
Vehicle Year: <b>2009</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 1:
Vehicle Make: <b>FORD - FORD</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 1:
Vehicle Model: <b>EPD</b>		Cit Chrg Code 2:
Vehicle Style: <b>SW</b>		Citation Charge 2:
Vehicle Color: <b>BLUE, DARK - DBL</b>		Citation Charge 3:
Vehicle Config: <b>01 - PASSENGER CAR</b>		Citation Charge 4:
Vehicle Defect:		
Vehicle Action:		
Tow: <b>2 - DISABLED - PRIVATELY ARRANGED</b>		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

**Accident Environment**

First Harmful Event Loc:	<b>Roadway Characteristics</b>
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>31 - ANIMAL</b>
Type:	
Workers Present:	

**Narrative**

Driver was driving east on Iowa 10 when a deer ran out in front of him. The driver struck the deer causing heavy front end damage, the airbags to deploy, and the vehicle to be un drivable. Vehicle appears to be a total loss.