

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Law Enforcement	Scene Investigated: <b>YES</b>	At Intersection with:
Case Number: <b>23-007663</b>	Report to All Drivers:	Div HWay Trvl Dir:
Date of Acc: <b>11/11/23</b>	Legal Intervention: <b>NO</b>	Distance 1:
Time of Acc: <b>20:49</b> Hrs.	Private Property: <b>NO</b>	Direction 1:
Name of Agency: <b>O'BRIEN COUNTY SHERIFF'S OFF</b>	County: <b>O'BRIEN - 71</b>	Distance 2:
Officer:	Acc Loc City:	Direction 2:
<b>DEPUTY JETT KORVER</b>	Acc Dir From City:	X-Coordinate: <b>00305606</b>
Badge #: <b>71-8</b>	Closest City:	Y-Coordinate: <b>04784054</b>
Report Date: <b>11/11/2023</b>	Miles From City:	Location Literal: <b>US 18 E MEASURING 1066 FEET</b>
Officer Notified: <b>20:50</b> Hrs.	Road, Street, HWay:	Description: <b>WEST FROM 100TH AVE</b>
Officer Arrived: <b>21:14</b> Hrs.	Definable Location:	
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>BLOM</b>	Bus Use:	Transported to:
First: <b>BRIANNE</b>		
Middle: <b>EVELETA</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>TERRIL</b>	Traffic Controls:	Special Veh Func:
State: <b>IA</b>		
Zip: <b>51364</b>	Point of Init Impact:	Emergency Status:
Suffix:		
Gender: <b>Female</b>	Most Damaged Area:	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Age: <b>34</b>	Undrriid/Ovrid:	
CDL: <b>YES</b>	Rpr/Rplc Cost: <b>\$1,500.00</b>	
License State: <b>IA</b>	Ext of Damage:	
License Class: <b>B</b>	First Event:	Carrier Name:
License Endorsmnt: <b>P - PASS</b>		Carrier Address:
License Restrictions: <b>K,B,M</b>	Second Event:	Carrier City:
Speed Limit:		Carrier State:
Seating Position:	Third Event:	Carrier Zip:
		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Driver Condition:	Fourth Event:	Number of Axles:
Alcohol Test Given: <b>NO</b>		HazMat Involvement:
Drug Test Given: <b>1 - NONE</b>	Most Harmful Event:	HazMat Placard:
Total Occupants: <b>2</b>	Abg Switch Stat:	Placard #:
Vehicle Year: <b>2017</b>	Abg Deploy:	HazMat Released?:
Vehicle Make: <b>RAM - RAM</b>	Trapped:	Converter Dolly:
Vehicle Model: <b>1500 LONGHORN</b>	Ejection:	GVWR:
Vehicle Style: <b>PK</b>	Ejection Path:	Cit Chrg Code 1:
Vehicle Color: <b>BLACK - BLK</b>	Occpnt Protect:	Citation Charge 1:
Vehicle Config: <b>02 - FOUR-TIRE TRUCK (PICK-UP)</b>		
Vehicle Defect:	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Citation Charge 2:
Vehicle Action:	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 2:
Tow: <b>2 - DISABLED - PRIVATELY ARRANGED</b>		Citation Charge 3:
Tow #:		
Initial Trvl Dir:		Citation Charge 4:
Vision Obscured:		

**Accident Environment**

First Harmful Event Loc:	<b>Roadway Characteristics</b>
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	
	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>31 - ANIMAL</b>
Type:	
Workers Present:	

**Narrative**

Unit one struck a deer on a bridge in the 7000-mile of 320th Street.

Diagram

---

