

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **24-000125**
 Date of Acc: **01/07/24**
 Time of Acc: **17:35** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY JETT KORVER**
 Badge #: **71-8**
 Report Date: **01/07/2024**
 Officer Notified: **17:36** Hrs.
 Officer Arrived: **17:38** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00275146**
 Y-Coordinate: **04785205**
 Location Literal: **US 18 E**
 Description:

Unit 001

Driver Name - Last: **MOSER**
 First: **ALLYSON**
 Middle: **LYNN**
 City: **SANBORN**
 State: **IA**
 Zip: **51248-0000**
 Suffix:
 Gender: **Female**
 Age: **30**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions: **B**
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2008**
 Vehicle Make: **FORD - FORD**
 Vehicle Model: **TAURUS**
 Vehicle Style: **SW**
 Vehicle Color: **RED - RED**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **02 - EAST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Drvr Distractions: **03 - MANUAL OPERATION OF AN ELECTRONIC COMMUNICATION D**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **12 - FRONT MIDDLE**
 Most Damaged Area: **12 - FRONT MIDDLE**
 Undrrid/Ovrid: **2 - UNDERRIDE, COMPARTMENT I**
 Rpr/Rplc Cost: **\$3,000.00**
 Ext of Damage: **3 - FUNCTIONAL DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **04 - DEPLOYED FRONT OF PERSON**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **1 - NOT APPLICABLE**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to: **SHELDON HOSPITAL**
 Transported by: **SHELDON AMBULANCE**
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Drvr: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1: **321.276**
 Citation Charge 1: **USE ELECTRONIC COMMUNICATION DEVICE - AG**
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: STERK	Bus Use:	Transported to:
First: ANDREW		
Middle: ROBERT	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: SHELDON		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51201-0000		
Suffix:	Point of Init Impact: 06 - REAR MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 06 - REAR MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 29	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$10,000.00	
License State: IA	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt: L		Carrier Address:
License Restrictions: B	Second Event:	Carrier City:
Speed Limit: 55	Third Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE		HazMat Involvement:
Total Occupants: 2		HazMat Placard:
Vehicle Year: 2024	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: CHEVROLET - CHEV		HazMat Released?:
Vehicle Model: TRX	Abg Switch Stat:	Converter Dolly:
Vehicle Style: UT	Abg Deploy: 01 - NOT APPLICABLE	GVWR:
Vehicle Color: WHITE - WHI	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR	Ejection: 1 - NOT APPLICABLE	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 03 - TURNING RIGHT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow: 1 - DRIVEN AWAY		
Tow #:	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 3:
Initial Trvl Dir: 02 - EAST	Died at Scene: 01 - NOT APPLICABLE	
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

Unit two was east on highway 18 slowing down to make a right turn onto their driveway. Unit one was also eastbound on highway 18. The driver of unit 1 was reading a text message on her phone and didn't realize that unit 2 was slowing down to turn. Unit 1 rear-ended unit 2.

